Post Slab Defect Inspection (No pre-slab carried out)

Provided By



Inspect365

Level 23, 727 Collins Street, Melbourne , VICTORIA , 3008, Australia P 1300 000 442 info@inspect365.com.au www.inspect365.com.au

Inspection Address

VICTORIA



Report Information

Client Information

Client Name Sample

Inspection Information

Report/Agreement # 1811211241401

Inspection Date: 18 Nov 2021

Inspection Time: 12:41 pm





Table of Contents

- 1. STAGE BUILDING INSPECTION REPORT
- 2. PLAN DETAILS
- 3. BUILDING WORKS INSPECTED
- 4. PLAN CONFIRMATION
- 5. CONFIRMATION





Summary Of Major Defects And Safety Hazards

Below Is A Summary Of Significant Items Requiring Immediate Action.

Section	Location	Name	Comment
PLAN CONFIRMATION	Findings	Layout	Does Not Conform With Plans. At the time of my inspection I noted a large amount of diagrams and measurements marked on the concrete slab, these markings are indicating areas in the slab that need to be cut back or extended, if this is the case I recommend the building surveyor assess to determine if this can be completed without compromising the structural integrity of the slab, steel work and waffle pods. I mark this as a major defect due to the severity of the problem.





Summary Of Minor Defects

Below Is A Summary Of Defects Other Than Major Defects.

Section	Location	Name	Comment
PLAN DETAILS	Property Plan Details	Obstructions and Inaccessible Areas	Concrete slab obstructing waffle pods, steel work and preparation for this stage.





STAGE BUILDING INSPECTION REPORT

BUILDING INSPECTION REPORT

Have Architectural or Structural Engineering Plans been provided for this inspection?

Yes

Where drawings have not been provided, the inspector cannot check specifications against the plan and can take no responsibility for any inconsistencies between the actual works inspected on site and the actual plans.

Weather at time of inspection:

Dry







PLAN DETAILS

Property Plan Details

Inspection Type

Foundation/Subfloor

Residential Building Type

Townhouse

Levels

Double Storey

Additions

Attached Garage

Main Building Subfloor Construction

Slab On Ground

Main Building Wall Consruction

Brick Veneer Construction

Main Building Roof Construction

Metal Sheeting

Obstructions and Inaccessible Areas

Concrete slab obstructing waffle pods, steel work and preparation for this stage.



















BUILDING WORKS INSPECTED

Description of Building Works Inspected

Description Of Building Works Inspected

Layout Foundation Material





PLAN CONFIRMATION

Findings

Layout

Does Not Conform With Plans.

At the time of my inspection I noted a large amount of diagrams and measurements marked on the concrete slab, these markings are indicating areas in the slab that need to be cut back or extended, if this is the case I recommend the building surveyor assess to determine if this can be completed without compromising the structural integrity of the slab, steel work and waffle pods.

I mark this as a major defect due to the severity of the problem.

















































































CONFIRMATION

Inspector's Statement Of Confirmation

Statement Of Confirmation

I confirm that the accessible and visually inspected works as described in this report, and inspected by me are consistent with the plans/drawings provided except where otherwise noted in this report.







The Inspection and Report was carried out by: John Sample

State License Number: DB-UXXXXX

Insurance Accreditation Number: Professional Indemnity Insurance Policy 2021-COXXXX-XXXXX

Contact the Inspector on: 04XX XXX XXX

For and on Behalf of: Inspect365





